

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0600-0700

0600 checked all vis a/m
 0700 checked all vis a/m

Bobby J. McWilliams

0700-0800

0700 checked all vis a/m
 0515 Secured main light
 0630 called crew

Bobby J. McWilliams

0800-1200

0800 morning colors
 0805 Saw too station work.
 0955 CG 40522 arrived unit with civilians.
 0900 CG 40522 reported.
 1000 bull work, main light, fog signal inspection.

R. A. Brown

1200-1600

1200 CHECKED VIS. a/m NONE VIS.
 1530 CG 40522 arrived this unit
 1540 SECURED FOG SIGNAL & GULL RKS BELL
 1545 CG 40522 Departed for cattle Hall with civilian workers.

R. A. Brown

1600-2000.

1600 checked all vis A/P.
 1645 Lits off main light, Gulls Rks #1 fog.
 signal

R. A. Brown EN-3

2000-2400

2000- checked all vis A/P, colors.

R. A. Heath

CERTIFIED TO BE CORRECT

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 - checked all vis A/N.
 0200 Secured fog signal and Bull Rks
 R.A. Heath

0400 checked all vis A/N.
 0600 Secured main light
 0630 Woke up crew.

R.A. Brown EN-3

0800 - 1200
 0800 Colors, turn too stations work.
 0800 check all vis A/N.
 0830 notified Castle Hill that fishing vessel
 joined from Point Judith was pulling cable
 from NE side of island.
 0845 CG 40522 arrived this unit with civilian workers.
 0900 Lite off emergency gen. for weekly test.
 0915 CG 40522 Departed.
 1000 Secured emergency gen. tested satisfactory.
 1045 CG 16585 Departed with Mc Williams BM-1
 going on liberty to Newport.
 1130 Secured for chow.

W.C. Radonick

1200 - 1600
 1200 checked all vis A/N.
 1230 CG 16585 Returned. Turn too stations work.
 R.A. Brown EN-3

1600 - 2000
 1600 checked all vis A/N.
 1600 Civilians departed for shore via their
 boat.
 1605 Secured stations work.
 1640 CG 16585 Departed for Newport to
 pick up Mc Williams BM-1.
 1730 CG 16585 Arrived with Mc Williams BM-1

R.A. Brown EN-3

2000 - checked all vis A/N. placed main light in
 operation, colors.

CERTIFIED TO BE CORRECT

R.A. Brown EN-3

(Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 - 0400
0000 checked all via A/P.

0400 - 0800
0400 checked all via A/P.
0600 Secured main light.
0630 Woke up crew

R. A. Brown EN-3

0800 - 1200
0800 checked all via A/P. Colors.
0805 Turn too station work.
0830 CG 40522 arrived this unit with civilian
workers.
0845 CG 40522 Departed for Newport.
0930 CG 16585 Departed for Newport with
Sadomaki FA going to pick up chow.
1015 CG 16585 arrived.
1130 Secured for chow.

R. A. Brown EN-3

1200 - 1600
1200 - checked all via A/P.
1230 Turn too station work.
1530 CG 16585 Departed for Newport.

1600 - 2000
1600 checked all via A/P.
1615 CG 40522 arrived.
1620 CG 40522 Departed with 20 civilian
workers.
1645 CG 16585 arrived.

R. A. Brown EN-3

2000 - 2400
2000 checked all via A/P, Colors, main light
placed in operation.
2150 Rec M 040104Z

CERTIFIED TO BE CORRECT

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000-0400
0000 checked all vis A/N.

R. A. Heath

0400-0800
0400 checked all vis A/N.
0600 Secured main light
0730 Woke up crew.

R. A. Brown EN-3

0800-1200
0800 checked all vis A/N.
0800 Colors.
1100 CG 16585 Departed for Newport to make
mail run and bring Sacowski FA on 48 Liberty.

R. A. Heath

1200-1600
1200 checked all vis A/N.
1300 CG 16585 Returned

R. A. Heath

1600-2000
1600- checked all vis A/N
1930 CG 36453 arrived unit with 26
16716 into tow for this unit.
1945 main light in operation.

R. A. Brown EN-3

2000-2400
2000 checked all vis A/N.

CERTIFIED TO BE CORRECT

Bobby H. McFarland
(Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 - 0400
0000 - checked all vis A/P.

R Brown EN-3

0400 - 0800
0400 checked all vis A/P.
0530 placed ~~main~~ fog signal and bell
Rks in operation.

0800 - 1200
0800 checked all vis A/P. color.
0830 Secured main light, fog signal and bell Rks.

1200 - 1600
1200 checked all vis A/P

1600 checked all vis A/P 1600-2000

1945 main light in operation
1945 Evening calars.

2000 - 0000
2000 checked all vis A/P
2200 checked all vis A/P

CERTIFIED TO BE CORRECT

Bobby S. McWilliams BN
(Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 started fog signal also Gull Rocks Bell
 0350 Secured fog signal also Gull Rks.

0400 - checked all ⁴⁰⁰⁻⁰⁸⁰⁰ vis. A/P.
 0545 LRD off #2 fog signal and Gull Rks.
 0638 Woke up crew.

0800 - 1200
 0800 checked all vis A/P. Colors.
 0805 Sum too station work
 0900 Bodonhi 1st return for Lbly.
 1000 Brow Ev 3 ~~departed~~ on 2nd day low.

1200-1600
 1200 Fog.
 1205 0656020 arrived unit with
 gun drums.

1230 0656020 Reported unit.
 1300 Sum too station work.
 1600 Secured for day.

1600-2000
 1600 checked all vis A/P
 1945 Evening colors
 1945 Started fog signal also main Light and Gull Rks

2000-
 2000 checked A/P none vis due to fog
 2200 checked all vis A/P fog.
 2400 Secured fog signal also Gull Rocks

CERTIFIED TO BE CORRECT

Bobby D. McArthur
 (Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 - 0400

0000 all #1 vis.

0330 Bull rock, station fog signal in operation.

0400 - 0800

R. A. Heath

0400 Vis 0 fog

0700 Held remote

0730 Switched from horn #2 a comp #2 to Horn
and comp #1

R. A. Heath

0800 - 1200

0806 Morning colors.

0915 turned to Station work, Heath, SA on 98th Liberty

0930 Secured fog sig. & gull the bell

0910 Received P/O 7 12422 display SCW.

1130 Secured for chew.

1200 - 1600

1200 Checked all vis & n

1230 Turn too Station work.

1600 Secured for day.

1600 - 2000

1600 Checked all vis & n.

1700 PS 40522 arrived to pick up Mr Perry's crew.

1945 Evening callers

1945 main light in operation.

2000 - 0000

2000 Checked all vis & n

CERTIFIED TO BE CORRECT

Bobby H. McWilliams
 (Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 checked all vis ⁰⁰⁰⁰⁻⁰⁴⁰⁰ a/m
 0200 checked all vis a/m

Betty S. Peterson

0400 checked all vis ⁰⁴⁰⁰⁻⁰⁸⁰⁰ a/m.
 0500 started fog signal also Aud Rocks
 0600 Rec'd S.O.C. P080750Z
 0630 called crew.

0800 checked all vis ⁰⁸⁰⁰⁻¹²⁰⁰ a/m
 0830 Secured fog signal also Aud Rocks and
 main light.
 1130 secured for show.

1200 checked all vis ¹²⁰⁰⁻¹⁶⁰⁰ a/m
 1230 turn too station work
 1345 CG 4052Z arrived to pick up Mr. Betty Crews
 1430 Rec'd R081818Z

1600-2000

1600 checked all vis a/m
 1630 Secured from work.
 1945 Evening color
 1945 main light in operation.

2000-0000

2000 checked all vis a/m
 2200 checked all vis a/m

CERTIFIED TO BE CORRECT

Betty S. Peterson
 (Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 checked all vis *q/m* 0000-0400

B. H. Williams

0900 checked all vis *q/m* 0400-0800

0915 Received P 090740 Z S.O.W.

0545 Secured main Light

0630 Called crew.

0800-1200

0800 Moring colors.

0805 Turn too station work.

1130 Secured for chow.

1200-1600

1200 checked all vis *q/m*

1800 Turn too station work.

Bobby A. Williams

1600-2000

1600 checked all vis *q/m*

1945 Evening colors

1945 main light cooperation

B. H. Williams

2000 checked all vis *q/m* 2000-0000

2200 checked all vis *q/m*

CERTIFIED TO BE CORRECT

Bobby A. Williams
(Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 - 0700

0000 checked all vis a/m
 0200 checked all vis a/m

R. A. Heath

0700 checked all vis a/m 0700 - 0800
 0545 Secured main light
 0630 Called crew

B. Stuebelian

0800 moving colors. 0800 - 1200

0805 Turn too station work.
 0805 checked all vis a/m.

1055 Started emergency gen. spr. on emergency power

1155 Secured emergency gen.

1200 Secured for power

1200 checked all vis a/m 1200 - 1600

1300 Turn too station work

4

1600 - 2000

1600 checked vis H₂

R. A. Heath

1615 Secured for station work.

1730 Main light on.

2000 - 0000

2000 evening colors.

2400 checked Vis H₂

R. A. Heath

CERTIFIED TO BE CORRECT

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 checked all vis & m 0000 - 0400

0200 checked all vis & m

R. A. Heath

0400 - 0800

0400 checked all vis & m

0545 Secured main light

0630 Held rivets

R. A. Heath

0900 Morning colors.

0900 - 1200

0930 turned to station work.

0900 Rec P 111240Z

1130 Secured for chow.

1200 checked all vis & m (1200 - 1600)

1230 turned to station work.

1600 Secured for day.

1600 - 2000

1600 checked all vis & m

1945 Evening colors

1945 main light in operation

2000 - 2400

2000 checked all vis & m

2200 checked all vis & m

CERTIFIED TO BE CORRECT

Robby H. McArthur
 (Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 checked all vis a/m 0000-0900

B. H. McWilliams

0700 checked all vis a/m 0400-0800

0545 secured main light
0800 morning colors.

R. A. Heath

0800-0900

0805 checked all vis a/m

R. A. Heath

1200 checked all vis a/m 1200-1600

1600 checked all vis a/m 1600-2000

1945 Evening colors

1945 main light in operation

2000-0000

R. A. Heath

2000 checked all vis a/m

R. A. Heath

0000 checked all vis a/m main light
extinguished

CERTIFIED TO BE CORRECT

Bobby A. McWilliams Bm1
(Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 - 0400

0000 checked all vis $\frac{1}{2}$ North Light
extinguished
R. A. Hunt

0400 - 0800

0400 checked all vis $\frac{1}{2}$ North Light
extinguished
R. A. Hunt

0545 main Light secured.

0630 Relit

0730 turned to station work
R. A. Hunt

0800 - 1200

0800 Morning colors.

0805 Turn to station work.

0900 Godomski FA Departed on 48 hr. Liberty.

1130 Secured for chow

1200 - 1600

1500 checked all vis $\frac{1}{2}$ m

1300 Turn to station work.

1600 Secured for day.

1600 - 2000

1600 checked all vis $\frac{1}{2}$ m

1945 Evening colors, CG 16855 to Cartel hid LBS

1945 main Light in operation

2000 - 0000

2000 checked all vis $\frac{1}{2}$ m

CERTIFIED TO BE CORRECT

Barby L. McWilliams
(Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 checked all vis q/m all OK.

0100 checked all vis q/m

B. J. McWilliams

0400 checked all vis q/m started to get fog (but did not come in as yet)

0515 started fog signal, also Hull Rocks

0630 called crew.

B. J. McWilliams

0800 checked all vis q/m none vis due to fog.

0800 morning colors.

0805 Turn too station work.

0900 secured fog signal, also Hull Rocks and Mine Light

1000 30402 arrived with Lt 3

1010 CG 30402 Depart for C.H. CBS.

1130 secured for dinner

1200 checked all vis q/m

1230 Turn too station work.

1300 Turn too station work.

1315 CG 30402 arrived to pick up Lt.

1600 secured for day

1600 checked all vis q/m

1945 Evening colors.

1945 Main Light in operation

2000 checked all vis q/m

2200 checked all vis q/m

2225 Reported to Earth Hill sighting of four WNW of station on shore of Tomestown

R. A. Heath

CERTIFIED TO BE CORRECT

Bobby J. McWilliams Bm1
(Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 checked all vis 9/m 0000-0400

0200 checked all vis 9/m

B. G. McWilliams

0400 checked all vis 9/m 0400-0800

0545 Secured main Light

0630 Called crew

A. A. Heath

0800 morning calars 0800-1200

0905 Turn too station work

W. Sackomisho

1200-1600

1200 CHECKED ALL VIS 9/m

1400 CG 36 ARRIVED FROM CASTLE HILL WITH

GADOMSKI FR HEATH SH DEPARTED ON 48 hr
LIBERTY

W. Sackomisho

1600-2000

1600 CHECKED ALL VIS 9/m

1930 MAIN LIGHT IN OPERATION

EVENING COCONS

W. Sackomisho

2000-2400

2000 CHECKED ALL VIS 9/m

W. Sackomisho

CERTIFIED TO BE CORRECT

Bobby G. McWilliams BM1
(Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000-0400

0000 CHECKED ALL OIS a/m
 0200 CHECKED ALL OIS a/m

W. Padomko

0400-0800

0400 CHECKED ALL OIS a/m
 0545 SECURED MAIN LIGHT

W. Padomko

0800-1200

0800 CHECKED OIS a/m MORNING COLORS
 TORN TO STATION WORK

0900 STARTED EMER. GEN (TEST)

1000 SECURED EMER. GEN.

1130 SECURED FOR CHOW.

R. A. Heath

1200-1600

1200 CHECKED ALL OIS a/m

1300 SWAN TOO STATION WORK.

1600 SECURED FOR DAY.

W. Padomko

1600-2000

1600 CHECKED ALL OIS a/m

1945 Evening colors.

1945 main light in operation

2000-2200

2000 checked all vis a/m
 2200 checked all vis a/m

W. Padomko

CERTIFIED TO BE CORRECT

Barney A. McArthur, Jr.
 (Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0600 Checked all vis a/m ⁰⁶⁰⁰⁻⁰⁷⁰⁰

0700 Checked all vis a/m

Bobby H. McWilliams Dr.

0700 Checked all vis a/m 0700-0800

0545 Secured ~~for~~ ~~for~~ main Light

0630 Called crew

R. A. Heath

0101 morning calls 0800 - 1200-

0805 Turn too station work

1130 Secured for crew

W. Sladomski

1200 Checked all vis a/m ¹²⁰⁰⁻¹⁶⁰⁰

1230 Turn too station work

1301 Heath R. A. SA Returned from 48hr. Security

1600 Secured for day.

1600-2000

W. Sladomski

1600 Checked all vis a/m

1930 main Light in operation

1945 Evening calls.

2000-0000

2000 Checked all vis a/m

2200 Checked all vis a/m

W. Sladomski

CERTIFIED TO BE CORRECT

Bobby H. McWilliams
(Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 - 0400

0000 CHECKED ALL VIS $\frac{1}{2}$ in0200 CHECKED ALL VIS $\frac{1}{2}$ in

w. Macdonald

0400 - 0800

0400 CHECKED ALL VIS $\frac{1}{2}$ in

0545 SECURED MAIN LIGHT

0630 REVICE

w. Macdonald

0800 - 1200

0800 CHECKED ALL VIS $\frac{1}{2}$ in MORNING COLORS

0805 TURN TO STATION WORK

1130 SECURED FOR CHOW

w. Macdonald

1200 - 1600

1200 CHECKED ALL VIS $\frac{1}{2}$ in

1230 TURN TO STATION WORK

1600 - 2000

R. A. Heath

1600 checked vis $\frac{1}{2}$ in

1930 main Light in operation.

2000 - 0000

R. A. Heath

2000 checked all vis $\frac{1}{2}$ in evening colour2200 checked all vis $\frac{1}{2}$ in0000 all vis $\frac{1}{2}$ in

CERTIFIED TO BE CORRECT

Bobby L. McWilliams
 (Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 - 0400.

0000 checked all vis A/n

R.A. Heath

0400 - 0800

0400 checked all vis A/n

R.A. Heath

0545 main light extinguished

0700 Revellie

0800 - 1200

0800 Turned to station work

0800 morning colors.

R.A. Heath

1200 - 1600

1200 checked vis A/n

1400 Godomski F4 departed on 48 hrs
Liberty.

1600 - 2000.

R.A. Heath

1600 checked vis A/n.

1615 Secured from Work.

1945 main light operation

2000 - 0000.

2000 evening colors.

R.A. Heath

2200 checked vis A/n.

CERTIFIED TO BE CORRECT

Betty D. MacIntyre
 (Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 - 0400

0000 checked all r in H/N

R. A. Heath

0400 - 0900

0400 checked all r in H/N

0600 main light secured.

0630 Routine

0730 turned to station work.

R. A. Heath

0900 - 1200

0900 morning tales.

R. A. Heath

1200 - 1600

1200 checked all r in H/N

R. A. Heath

1700 turned to station work.

1600 - 2000

1600 checked all r in H/N.

1600 Log signals in opening

1615 Secured from station work.

1700 Secured Log signals.

R. A. Heath

1945 Main light in operation

1945 Evening tales

2000 - 0000

2000 checked all r in H/N

2200 checked all r in H/N

CERTIFIED TO BE CORRECT

Bobby J. McFarland
 (Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0600 checked all mis ⁶⁰⁰⁰⁻⁰⁸⁰⁰ a/m

0200 checked all mis a/m

0500 checked all mis a/m ⁰⁷⁰⁰⁻⁰⁸⁰⁰

0630 secured main light

0630 called crew.

0800 morning colors.

0800-1200

0805 sum too station work.

1130 secured for crew.

1200-1600

1200 checked all mis a/m

1300 sum too station work.

1315 Hadomaki returned from Liberty.

1600 secured for day.

1600-2000

1600 checked all mis a/m

1900 main light inspection

1900 Evening colors.

2000-0000

2000 checked all mis a/m

2200 checked all mis a/m

CERTIFIED TO BE CORRECT

Betty McIntosh
(Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 checked all vis ⁰⁰⁰⁰⁻⁰⁴⁰⁰ a/m

0200 checked all vis a/m

0400 checked all vis ⁰⁴⁰⁰⁻⁰⁸⁰⁰ a/m

0605 secured all vis a/m secured main light

0630 called crew.

0800 morning calcs. ⁰⁸⁰⁰⁻¹²⁰⁰

0805 saw too station work.

1130 scanned for chaw

1200 checked all vis a/m ¹²⁰⁰⁻¹⁶⁰⁰

1230 saw too station work.

1600 secured for day.

¹⁶⁰⁰⁻²⁰⁰⁰

1600 checked all vis a/m

1905 Main Light in operation

1915 Evening calcs.

1945 called distill. hbl LBS about Sail Boat aground
on NW end of Island

2000 checked all vis a/m ²⁰⁰⁰⁻⁰⁰⁰⁰

2200 checked all vis a/m

CERTIFIED TO BE CORRECT

Bobby J. McArthur
(Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 checked all vis & m
0200 checked all vis & m

W. Hadomako

0400 - 0800

0400 CHECKED ALL VIS & m
0600 SECURED MAIN LIGHT

W. Hadomako

0800 - 1200

0800 CHECKED ALL VIS & m MORNING COLORS
TURN TO STATION WORK

1430 SECURED FOR CHOW

W. Hadomako

0900 HEATH SA DEPARTED ON 4 hr CIPHER

1200 - 1600

1200 CHECKED ALL VIS & m

1230 TURN TO STATION WORK

1600 - 2000

1600 SECURED FOR DAY

1600 - 2000

1600 CHECKED ALL VIS & m

1945 MAIN LIGHTING OPERATION

1945 EVENING COLORS.

2000 CHECKED ALL VIS & m 2000 - 0000

2200 CHECKED ALL VIS & m

CERTIFIED TO BE CORRECT

Bobby L. McWilliams, Sr.
(Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 - 0400

0000 checked all vis q/m

0200 checked all vis q/m

B. H. McWilliam

0400 - 0800

0400 checked ALL vis A/M

0615 secured MAINE Light.

0630 called crew

B. H. McWilliam

0800 - 1200

0800 Morning patrol, checked ALL vis A/M

0805 Turn To STATION WORK

1130 Secured For chow.

1200 - 1600

1200 checked ALL vis A/M

1230 Turn To STATION WORK.

1600 Secured FOR DAY

1600 - 2000

1600 checked all vis q/m

1915 Main Light in operation, checked all vis q/m

1915 Evening patrol.

2000 - 0000

2000 checked all vis q/m

2200 checked all vis q/m

CERTIFIED TO BE CORRECT

Bobby D. McWilliam Bn.
(Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 CHECKED ALL VIS ^{0000 - 0900} A/N

0200 CHECKED ALL VIS A/N

^{0400 - 0800}

0400 CHECKED ALL VIS ^{a/m}

0615 SECURED MAIN LIGHT

0630 CALLED CREW

^{0800 - 0200}

0800 CHECKED ALL VIS ^{a/m} MORNING COLORS

0805 TORN TO STATION WORK

0200 HEATH SH RETURNED FROM 48 HR LIBERTY

1130 SECURED FOR SHOW.

^{1200 - 1600}
1200 CHECKED ALL VIS ^{a/m}

1230 TURN TO STATION WORK

1600 SECURED FOR DAY.

^{1600 - 2000}

1600 CHECKED ALL VIS ^{a/m}

1945 MAIN LIGHT IN OPERATION

1915 Evening Colors.

^{2000 - 0000}

2000 CHECKED ALL VIS ^{a/m}

2200 CHECKED ALL VIS ^{a/m}

CERTIFIED TO BE CORRECT

Boyle D. McWilliams, Sr.
(Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 checked all vis ^{0000 - 0900} y/m

0200 checked all vis y/m

0400 checked all vis y/m

0900 - 0801

0500 Started fog signal also Hull Rocks Bell.

0800 checked all vis y/m (fog) 0800 - 1200

0915 Secured main light, also fog signal and shell
Rocks Bell.

1200 checked all vis ^{Holiday Counted} y/m 1200 - 1600

1600 checked all vis y/m 1600 - 2000

1915 main light in operation

1915 Evening Calm.

2000 checked all vis y/m 2000 - 0000

2200 checked all vis y/m

CERTIFIED TO BE CORRECT

Bobby J. MacWilliams
(Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 - checked all vis a/m 0000-0400

0200 checked all vis a/m

0400 checked all vis a/m 0400-0800

0615 secured main light

0630 called crew.

0800 checked all vis a/m 0800-1200

0800 morning colors

0805 turn too station work.

0930 Hull rocks - main light - fog signal in operation.

1015 secured main light Hull Rocks, and fog signal

1030 Brown EN3 returned from 20 days leave

1130 secured for check.

1200 checked all vis a/m 1200-1600

1230 turn too station work

1600 secured station work

1600-2000

1600 checked all vis a/m.

1915 main light in operation

1915 Evening colors.

2000-0000

2000 checked all vis a/m

2200 checked all vis a/m

2245 started Hull Rocks, also fog signal

CERTIFIED TO BE CORRECT

Bobby L. McWilliams
(Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000 - 0400
0000 checked all vis A/N FOG signal in operation.

LPA Brown EN-3

0400 - 0800
0400 checked all vis A/N FOG signal in operation.
0515 Secured fog signal and Gull Rks.
0615 Secured main light.
0630 Woke up crew.

LPA Brown EN-3

0800 - 1200
0800 Checked all vis A/N colors.
0805 Turn to station work.
0930 Foodmaker FA departed for liberty.
1130 Secured for chow.

B. J. McWilliam

1200 - 1600
1200 Checked all vis A/N.
1230 Turn to.
1515 Started fog signal also Gull Rocks
and Main Light.

1600 - 2000
1600 Checked all vis a/m none vis due to fog.
1700 Secured fog signal, Gull Rocks
and Main Light.
1815 Rec PZBZ100Z + PZBZ148Z

2000 - 0000
2057 Rec OZ90026
2200 Checked all vis a/m

CERTIFIED TO BE CORRECT

Bobby L. McWilliam Bx1
(Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000-0400
0000 checked all vis A/N.

R. H. Brown EN-3

0400-0800
0400 checked all vis A/N.
0615 Secured main light.
0630 Woke up crew.
0750 Received P2916362

B. S. McWhorter

0800 - 1200
0800 checked all vis A/N
0805 Turn too station work.
1130 Secured for chow.

1200-1600
1200 checked all vis A/N
1230 Turn too station work
1600 Secured for day.

1600-2000
1600 checked all vis A/N

1842 Rev 792130Z

1915 Evening calcs

1915 Main light in operation, checked all vis
A/N.
R. H. Brown EN-3

2000-0000
2000 checked all vis A/N
2200 checked all vis A/N

B. S. McWhorter

CERTIFIED TO BE CORRECT

Betty S. McWilliams Bm1.
(Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000-0400
0000- checked all vis A/W.

0400-0800
0400 checked all vis A/W.
0615 secured main light
0630 woke up crew.

0800-1200
0800- checked all vis A/W. colors
0810 turn too station work
0900 Heath, R. H. (SA) departed on 15 days leave, Brown on
on 4th Liberty. Sadomatti FA. Returned from
Liberty.
1130 secured for crew.

1200-1600
1200 checked all vis 4m [1200-1600]
1230 turn too station work,
1600 secured for day

1600-2000
1600 checked all vis 4m
1915 main Light in operation
1915 lining colors

2000-0000
2000 checked all vis 4m
2200 checked all vis 4m

R. A. McWilliams B.M.

CERTIFIED TO BE CORRECT

Bobby A. McWilliams B.M.
(Officer in Charge)

RECORD OF THE MISCELLANEOUS EVENTS OF THE DAY

0000-0900

0000 checked all vis q/m
 0200 checked all vis q/m
 0400 checked all vis q/m 0700-0800
 0500 Received P 310820 Z S.O. to Landed.
 0615 Secured main Light.
 0630 called crew.

R. J. McWilliams Bmt

w. Nakomichi

0800-1200

0800 morning calms.
 0805 Sum too station work.
 0810 WABL 403 (Span) arrived to give water (10,000) and fuel (\$500)
 1100 WABL 403 (Span) departed unit.
 1130 SECURED FOR CHOW

w. Nakomichi

1200-1600

1200 CHECKED ALL VIS q/m
 1230 TURN TO STATION WORK
 1600 SECURED FOR DAY

1600-2000

1600 checked all vis q/m

2000-2400

2000 CHECKED ALL VIS q/m
 2040 BPSHOPS MKS BOOY OUT NA 74
 2200 checked all vis q/m

CERTIFIED TO BE CORRECT

B. J. McWilliams Bmt
 (Officer in Charge)